




# Machine Pit Floor Plates


Millersburg, OR



Pillar Consulting Group, Inc. was asked to develop a plan to replace a failing steel floor covering a large machine foundation. We developed a BIM model of the existing machine pit and utility trenches to help the client better understand our proposed design for a new steel floor plate system that would be capable of supporting their 10 ton forklifts.

Owner:  
**Confidential**

Pillar's Responsibilities:  
**Structural Engineering**  
**BIM Model**



**BUILDING INFORMATION MODELING**

for more information contact Joe McCormick, P.E. at 541-752-9202 ext. 112



www.pillar-inc.com